polyga

HDI COMPACT USB
QUICK START GUIDE

1

FLEXSCAN3D

DOWNLOAD FLEXSCAN3D
Log in to our website at
https://www.polyga.com/my-account/
to download and install FlexScan3D.

2

CONNECT YOUR SCANNER
Plug in the power (12V DC) and the USB cable
into the scanner and your computer.
Turn the scanner on.

3

ADD YOUR SCANNER
Start FlexScan3D.
Under the Scanners tab, select New to add a
scanner.
Select your Scanner Type and click OK.
Select the Project tab to begin scanning.

NOTE: Always power down the scanner before removing cables from the scanner.